

SERVICE BULLETIN

RELEASE DATE: April 10, 2019

SUBJECT: VT651/801 Winterization Tips

STEP 1. Drain the tank by removing the caps at the rear. Reinstall once empty.



STEP 2. Open valve on side of hopper.




SERVICE BULLETIN

RELEASE DATE: April 10, 2019

SUBJECT: VT651/801 Winterization Tips

STEP 3. Close valve once empty

STEP 4. Drain water filter and also the hose using the ball valve.



STEP 5. Push in on rod and drain



SERVICE BULLETIN

RELEASE DATE: April 10, 2019

SUBJECT: VT651/801 Winterization Tips

STEP 6. Start up chassis, allowing it to build full air pressure.

STEP 7. Go to the Main Menu Screen and select #11.



STEP 8. Select #4 and follow on-screen instructions.



SERVICE BULLETIN

RELEASE DATE: April 10, 2019

SUBJECT: VT651/801 Winterization Tips

STEP 9. Run through this purge exercise a minimum of **TWO** times making sure that no additional water is being expelled. If you are still seeing water repeat an additional time.

STEP 10. If unit has Supawash remove center plug on pump and make sure there is no water present. If you see any, remove inlet hose and allow to drain.

